

Summary of Facility Information in the County of Powell

Owner Name and Address: Dennis Leo Schowengerdt 520 Main St Deer Lodge MT 59722 Phone: (406) 846-3545

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3904312	Main Street Service Inc	520 Main St	Deer Lodge	59722	(406) 846-3545

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently In Use	3944	4/18/1974 32 / No	Diesel 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
2 / 01 Currently In Use	3945	4/18/1974 32 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
3 / 02 Currently in Use	3844	4/18/1974 32 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Powell

Owner Name and Address: Fickler Oil Co Inc 725 Maverick Ln Deer Lodge MT 59722 Phone: (406) 846-3970

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3907856	I 90 Auto Truck Plaza	132 Interstate 90 Interchange	Deer Lodge	59722	(406) 846-3970

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
10 / 10 Currently In Use	3612	12/1/1998 07 / No	Diesel 15,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
11 / 11 Currently In Use	3613	12/1/1998 07 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
12 / 12 Currently In Use	4436	6/1/2001 05 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>D E F H I J K L</div> </div>	Yes Yes Yes Yes
13 / 13 Currently In Use	4437	6/1/2001 05 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>D E F H I J K L</div> </div>	Yes Yes Yes Yes
14 / 14 Currently In Use	4847	6/26/2003 03 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
15 / 15 Currently In Use	4848	6/26/2003 03 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Powell

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3908694	Town Pump Inc Deer Lodge	203 N Main St	Deer Lodge	59722	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2589	4/14/1977 29 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2590	4/14/1977 29 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	2591	4/14/1977 29 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	2592	7/30/1998 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently In Use	4282	9/15/2000 05 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently In Use	4283	9/15/2000 05 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Powell

Owner Name and Address: Robert Hollenback 141 N Interchange Deer Lodge MT 59722 Phone: (406) 846-1443

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3910909	Country Village BP Station	141 N Interchange	Deer Lodge	59722	(406) 846-1443

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently In Use	767	4/13/1989 17 / No	Gasoline 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	768	11/19/1998 07 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	769	11/19/1998 07 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Powell

Owner Name and Address: Broken Circle Ranch Co Inc 3987 Eastside Road Deer Lodge MT 59722 Phone: (406) 846-9318

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3913744	Broken Circle Ranch Co Inc	400 Eastside Road	Deer Lodge	59722	(406) 846-9614

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																								
1 / 01 Currently in Use	4624	6/1/1996 10 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L		B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
2 / 02 Currently in Use	4625	6/1/1996 10 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L		B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Powell

Owner Name and Address: Bill Thomas PO Box 15 Elliston MT 59728 Phone: (406) 492-6391

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3905196	Elliston Store	10 US Highway 12	Elliston	59728	(406) 492-6391

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																									
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																									
3 / 03 Currently in Use	3856	5/6/1985 21 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
4 / 04 Currently in Use	3857	5/6/1985 21 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Powell

Owner Name and Address: Garrison Mercantile & Post Office Inc
PO Box 636 Garrison MT 59731 Phone: (406) 846-3505

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3903405	Garrison Mercantile & Post Office Inc	Interstate 90 & US Highway 12	Garrison	59731	(406) 846-9961

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01	3934	5/5/1981	Gasoline	Cathodically Protected Steel	Galvanized Steel	Safe Suction	A B C <input checked="" type="radio"/> E F G H I J K L	Yes
Temporarily Out of Use		25 / No	5,000	Lined Interior/Impressed Curr	Impressed Current		B D E F G H I <input checked="" type="radio"/> K L	Yes Yes Yes
2 / 02	3935	5/5/1981	Gasoline	Cathodically Protected Steel	Galvanized Steel	Safe Suction	A B C <input checked="" type="radio"/> E F G H I J K L	Yes
Temporarily Out of Use		25 / No	5,000	Lined Interior/Impressed Curr	Impressed Current		B D E F G H I <input checked="" type="radio"/> K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Powell

Owner Name and Address: Blackfoot Commercial Co LLC 722 Pine PO Box 89 Ovando MT 59854 Phone: (406) 793-5555

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3902276	Blackfoot Commercial Co LLC	722 Pine St	Ovando	59854	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S07 Currently in Use	3362	6/1/1996 10 / Ye	Diesel 1,000	Other None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
2 / S08 Currently in Use	3363	6/1/1996 10 / Ye	Gasoline 3,000	Other None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
3 / S09 Currently in Use	3364	6/1/1996 10 / Ye	Gasoline 1,000	Other None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed